



MERCEDES Vito: 1FAN354			
Vinnnumber:	WDF63960313811543	Versionname:	VITO 113 B/F MWB A2 136PK
First Registrationdate:	7/05/2013	Fiscalpower:	
Expertise Mileage:	182246	Power Kw:	100
Bodytype:	Transporter	Body color:	White
Gearbox:	MAN 6 VIT	Paint type:	Opaque
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2507
Number of doors:	5		
Number of seats:	3		
Number head rests:	3		
Rims summer:	Steel		
Category:	Light Commercial Vehicle		
Oil level:	OK		

Options	
Radio CD	
Windows electric F	
Type of headlighting	Headlighting Halogen
Type of Lining	Lining fabrics
Type of climate control	Manual climate control

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
	195/65/16/100 T Steel			
Summer tyres:	Fr.L.	Bridgestone: 4 mm	Fr.R.	Bridgestone: 4 mm
	Re.L.	Bridgestone: 5 mm	Re.R.	Bridgestone: 5 mm

Assistance equipment			
Spare wheel	Yes	Jack	Yes
Total cost ex VAT			1175,58
Roof, Bump(s), LI - Repair and paint (complete)			361,13



Bumper R, Bump(s), Smart repair			110,64
---------------------------------	--	--	---------------



Bonnet, Stone chip(s), Acceptable 0,00

No pictures to display

Bodywork, Not original part, Acceptable 0,00

No pictures to display

Tailgate, Bump(s), LI - Repair and paint (complete) 362,02



Front bumper, Scratch(es), Smart repair 110,64



Wing R R, Bump(s), LI - Repair and paint (complete) 231,15



Windscreen, Scratch(es), Acceptable 0,00

No pictures to display

Wing F R, Scratch(es), Acceptable 0,00

No pictures to display