



**OPEL Insignia: 1FXG430**

Vinnumber:	<b>W0LGM8ER2E1038452</b>	Versionname:	<b>INSIGNIA BRE ecoFLEX Edition 120PK</b>
First Registrationdate:	<b>26/11/2013</b>	Fiscalpower:	
Expertise Mileage:	<b>184257</b>	Power Kw:	<b>88</b>
Bodytype:	<b>Break</b>	Body color:	<b>Brown</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:		Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>1433</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Windows electric F	Central consol F
Windows electric R	Luggage cover
Cruise Control	Front parking sensors
Steering wheel multifunction	Rear parking sensors
Radio multimedia	
Type of headlighting:	<b>Headlighting Halogen</b>
Type of GPS:	<b>GPS big screen color</b>
Type of Lining:	<b>Lining fabrics</b>
Type of climate control:	<b>Autom climate control</b>

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>225/55/17/101 Y LightMetal</b>			
Summer tyres:	Fr.L.	<b>Semperit: 8 mm</b>	Fr.R.	<b>Semperit: 8 mm</b>
	Re.L.	<b>Semperit: 8 mm</b>	Re.R.	<b>Semperit: 8 mm</b>

**Assistance equipment**

Spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
-------------	------------	------	------------

Total cost ex VAT	<b>1252,97</b>
-------------------	----------------

Door R R, Bump(s) and scratch(es), LI - Repair and paint (complete)	<b>318,35</b>
---	---------------



Tailgate, Scratch(es), LI - Repair and paint (complete)	<b>301,68</b>
---	---------------





Door R L, Scratch(es), Acceptable 0,00

No pictures to display

Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Bumper grille F L, Strained , Smart repair 110,64



Sill outer R, Bump(s) and scratch(es), LI - Repair and paint (complete) 310,50



Windscreen, Damaged, E - Replace 0,00

