


MERCEDES C: 1FGK680

Vinnnumber:	WDD2042001G161978	Versionname:	C BRE 180 CDI BlueEFF. S&S 120PK
First Registrationdate:	21/06/2013	Fiscalpower:	
Expertise Mileage:	148188	Power Kw:	88
Bodytype:	Break	Body color:	Brown
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4824
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD		Central consol F
GPS storage	HD	Luggage cover
GPS storage		Front parking sensors
Windows electric F		Rear parking sensors
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining leather	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/45/17/91 W LightMetal			
Summer tyres:	Fr.L.	Pirelli: 7 mm	Fr.R.	Pirelli: 7 mm
	Re.L.	Pirelli: 6 mm	Re.R.	Pirelli: 6 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
Total cost ex VAT			360,00
Alloy rim R L, Scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Door panel F L, Deformed, Acceptable			0,00
<i>No pictures to display</i>			
Wing R L, Bump(s), Acceptable			0,00
<i>No pictures to display</i>			
Alloy rim F L, Scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Seat cover F L, Bad repair, E - Replace			360,00



Door R L, Bump(s), Acceptable	0,00
<i>No pictures to display</i>	
Roof pillar L, Bump(s), Acceptable	0,00
<i>No pictures to display</i>	
Bumper corner R L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	