


MERCEDES B: 1KRS669

Vinnumber:	WDD2462121J340623	Versionname:	1.5 B 180 CDI STYLE
First Registrationdate:	17/06/2015	Fiscalpower:	
Expertise Mileage:	184945	Power Kw:	80
Bodytype:		Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1404
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Front parking sensors	
Steering wheel multifunctional		Rear parking sensors	
Radio multimedia		Type of Tow bar	Tow bar fixed
Type of headlighting	Headlighting LED		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/55/16/91 V LightMetal				
Summer tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 6 mm	Re.R.	Michelin: 6 mm

Assistance equipment

Repair kit	No	Compressor	No
Total cost ex VAT			672,33
Ignition key, Missing, E - Replace			150,00
<i>No pictures to display</i>			
Roof, Bump(s), Acceptable			0,00
<i>No pictures to display</i>			
Boot carpet, Damaged, E - Replace			100,00



Bumper R, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Front bumper, Scratch(es), LI - Repair and paint (complete)		211,80



Tyre repair kit, Missing, E - Replace	210,53
---------------------------------------	--------



Maintenance book, Missing, E - Replace	0,00
--	------

No pictures to display