


BMW 5 BERLINE: 1KKD892

| | | | |
|------------------------------------|--------------------------|--------------|-------------------------|
| Vinnumber: | WBA5E51050G065353 | Versionname: | 2.0 520D (120KW) |
| First Registrationdate: | 19/05/2015 | Fiscalpower: | |
| Expertise Mileage: | 61687 | Power Kw: | 120 |
| Bodytype: | | Body color: | Dark Grey |
| Gearbox: | Automatic | Paint type: | Metalic |
| Transmission: | | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | 3213 |
| Number of doors: | 4 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

Options

| | |
|--------------------------------|------------------------------|
| Radio CD | Sun Roof electric |
| Windows electric F | Central consol F |
| Windows electric R | Front parking sensors |
| Cruise Control | Rear parking sensors |
| Steering wheel multifunctional | |
| Seats F heated | |
| Radio multimedia | |
| Type of headlighting: | Headlighting Halogen |
| Type of GPS: | GPS big screen color |
| Type of Lining: | Lining leather |
| Type of climate control: | Autom climate control |
| Head-up Display | |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|---------------|----------------------------------|-----------------------|-------|-----------------------|
| | 225/55/17/97 Y LightMetal | | | |
| Summer tyres: | Fr.L. | Michelin: 5 mm | Fr.R. | Michelin: 5 mm |
| | Re.L. | Michelin: 5 mm | Re.R. | Michelin: 5 mm |

Assistance equipment

| | | | |
|------------|------------|------------|------------|
| Repair kit | Yes | Compressor | Yes |
|------------|------------|------------|------------|

| | |
|-------------------|---------|
| Total cost ex VAT | 1260,18 |
|-------------------|---------|

| | |
|---|--------|
| Front bumper, Scratch(es), LI - Repair and paint (complete) | 254,16 |
|---|--------|



| | |
|---|--------|
| Bumper R, Scratch(es), LI - Repair and paint (complete) | 254,16 |
|---|--------|



Wing R L, Bump(s) and scratch(es), LI - Repair and paint (complete) 369,84



Door R L, Scratch(es), LI - Repair and paint (complete) 382,02

