



**OPEL Astra: 1FEY454**

Vinnnumber:	<b>W0LPC6DA7D1115222</b>	Versionname:	<b>ASTRA BER ecoFLEX Essentia S&amp;S 95PK</b>
First Registrationdate:	<b>11/06/2013</b>	Fiscalpower:	
Expertise Mileage:	<b>67751</b>	Power Kw:	<b>70</b>
Bodytype:	<b>Hatchback</b>	Body color:	<b>Black</b>
Gearbox:	<b>MAN 5 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>4304</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		

**Options**

Radio CD	Luggage cover
Windows electric F	
Radio multimedia	
Type of headlighting:	<b>Headlighting Halogen</b>
Type of Lining:	<b>Lining fabrics</b>
Type of climate control:	<b>Manual climate control</b>

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>215/60/16/95 V Steel</b>			
Summer tyres:	Fr.L.	<b>Continental: 4 mm</b>	Fr.R.	<b>Continental: 4 mm</b>
	Re.L.	<b>Continental: 5 mm</b>	Re.R.	<b>Continental: 5 mm</b>

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
------------	------------	------------	------------

<b>Total cost ex VAT</b>	<b>701,68</b>
--------------------------	---------------

<b>Roof, Chemical polution, LI - Repair and paint (complete)</b>	<b>481,50</b>
--	---------------



<b>Wing R R, Bump(s) and scratch(es), Acceptable</b>	<b>0,00</b>
--	-------------

*No pictures to display*

<b>Tailgate, Scratch(es), Acceptable</b>	<b>0,00</b>
--	-------------

*No pictures to display*

<b>Wing F R, Bump(s) and scratch(es), LI - Repair and paint (complete)</b>	<b>220,18</b>
--	---------------





Bonnet, Bump(s) and scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Bodywork, Not original part, Acceptable	0,00
<i>No pictures to display</i>	
Wing R L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	