



**RENAULT Kangoo Express: MC9535**

Vinnnumber:	<b>VF1FW1AB545468196</b>	Versionname:	<b>KANGOO Expr. Gr.Confort</b>
First Registrationdate:	<b>6/06/2011</b>	Fiscalpower:	<b>68PK</b>
Expertise Mileage:	<b>159538</b>	Power Kw:	<b>50</b>
Bodytype:	<b>Transporter</b>	Body color:	<b>White</b>
Gearbox:	<b>MAN 5 VIT</b>	Paint type:	<b>Opaque</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>1223</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>2</b>		
Number head rests:	<b>2</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Light Commercial Vehicle</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

- Windows electric F
- Radio multimedia
- Type of headlighting **Headlighting Halogen**
- Type of Lining **Lining fabrics**

**Limited Technical Inspection**

Tires wear profile	<b>OK</b>	Battery functioning	<b>Yes</b>
Idle position	<b>OK</b>	Power steering	<b>Yes</b>
Engine startingtime	<b>OK</b>	Sound engine	<b>OK</b>
Exhaust gass	<b>OK</b>	Clutch test	<b>OK</b>
Handbrake	<b>OK</b>	Wiper fluid level	<b>OK</b>
		Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>195/65/15/91 T Steel</b>			
Summer tyres:	Fr.L.	<b>Michelin: 3 mm</b>	Fr.R.	<b>Michelin: 3 mm</b>
	Re.L.	<b>Michelin: 5 mm</b>	Re.R.	<b>Michelin: 5 mm</b>

**Assistance equipment**

Emergency spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
-----------------------	------------	------	------------

<b>Total cost ex VAT</b>	<b>1137,67</b>
<b>Tailgate, Bump(s) and scratch(es), LI - Repair and paint (complete)</b>	<b>362,02</b>



<b>Dashboard, Scratch(es), Acceptable</b>	<b>0,00</b>
<i>No pictures to display</i>	
<b>Door panel F R, Scratch(es), Acceptable</b>	<b>0,00</b>
<i>No pictures to display</i>	
<b>Headlight R, Stain, Acceptable</b>	<b>0,00</b>
<i>No pictures to display</i>	
<b>Floor covering F L, Damaged, E - Replace</b>	<b>237,00</b>



Bonnet, Bump(s), Acceptable	0,00
<i>No pictures to display</i>	
Wing R R, Bump(s) and scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Seat cover F L, Worn, Acceptable	0,00
<i>No pictures to display</i>	
Door R R, Bump(s) and scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Rear window, Scratch(es), E - Replace	307,50



Headlight L, Stain, Acceptable	0,00
<i>No pictures to display</i>	
Front bumper, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Bumper R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Door F L, Bump(s) and scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Wing R L, Bump(s), LI - Repair and paint (complete)	231,15

