


**RENAULT Scenic: 1FWD778**

Vinnnumber:	<b>VF1JZ14K649871057</b>	Versionname:	<b>SCENIC Energy Life 110PK</b>
First Registrationdate:	<b>15/11/2013</b>	Fiscalpower:	
Expertise Mileage:	<b>152228</b>	Power Kw:	<b>81</b>
Bodytype:		Body color:	<b>Black</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>OK</b>	Parking lot:	<b>2427</b>
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD		Central consol F
GPS storage		Luggage cover
GPS storage	<b>SD</b>	Front parking sensors
Windows electric F		Rear parking sensors
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Alarm		
Type of headlighting	<b>Headlighting Halogen</b>	
Type of GPS	<b>GPS big screen color</b>	
Type of Lining	<b>Lining fabrics</b>	
Type of climate control	<b>Manual climate control</b>	

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>205/60/16/92 H LightMetal</b>			
Summer tyres:	Fr.L.	<b>Michelin: 5 mm</b>	Fr.R.	<b>Michelin: 5 mm</b>
	Re.L.	<b>Michelin: 5 mm</b>	Re.R.	<b>Michelin: 5 mm</b>

**Assistance equipment**

Spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
-------------	------------	------	------------

Total cost ex VAT	<b>1657,99</b>
-------------------	----------------

Door frame F R, Bump(s) and scratch(es), It - Spot repair	<b>115,56</b>
---	---------------



Front bumper, Scratch(es), Acceptable	<b>0,00</b>
---------------------------------------	-------------

No pictures to display

Door R L, Scratch(es), Acceptable	<b>0,00</b>
-----------------------------------	-------------

No pictures to display

Door F R, Scratch(es), Acceptable	<b>0,00</b>
-----------------------------------	-------------

No pictures to display

Alloy rim F R, Damaged, E - Replace

235,20



Wing R L, Bump(s), PDR - Knock out without painting

82,80



Bumper corner R L, Bump(s) and scratch(es), It - Spot repair

115,56



Wing R R, Bump(s) and scratch(es), LI - Repair and paint (complete)

308,20



Wing F R, Scratch(es), Acceptable

0,00

No pictures to display

Door frame F L, Bump(s) and scratch(es), It - Spot repair

115,56



Bumper R, Bump(s), Smart repair

110,64



Door R R, Bump(s) and scratch(es), It - Spot repair

115,56



Interior, Stain, Cleaning

25,00



Tailgate, Scratch(es), Acceptable

0,00

No pictures to display

Bumper corner R R, Scratch(es), It - Spot repair 115,56



Door F L, Bump(s) and scratch(es), LI - Repair and paint (complete) 318,35



Door R R, Bump(s) and scratch(es), Acceptable 0,00

*No pictures to display*