



OPEL Astra: 1FFW108

Vinnumber:	W0LPC6DAXD1104232	Versionname:	ASTRA BER ecoFLEX Essentia S&S 95PK
First Registrationdate:	18/06/2013	Fiscalpower:	
Expertise Mileage:	35712	Power Kw:	70
Bodytype:		Body color	Black
Gearbox:	MAN 5 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Steel
Fueltype:	Diesel	Oil level	OK
Maintenance	OK	Parking lot	3121
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Steel		
Category	Passenger Car		
Oil level	OK		

Options

Radio CD		Luggage cover	
GPS storage			
GPS storage		SD	
Windows electric F			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	215/60/16/95 V Steel			
Summer tyres:	Fr.L.	Continental: 5 mm	Fr.R.	Continental: 5 mm
	Re.L.	Fulda: 5 mm	Re.R.	Fulda: 5 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT	537,88
-------------------	---------------

Door R R, Scratch(es), Acceptable	0,00
-----------------------------------	-------------

No pictures to display

Inner door handle F L, Missing, E - Replace	36,00
---	--------------



Bonnet, Chemical polution, LI - Repair and paint (complete)	290,08
---	---------------





Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Wing F R, Scratch(es), Acceptable 0,00

No pictures to display

Bodywork, Not original part, Acceptable 0,00



Front bumper, Scratch(es), Acceptable 0,00

No pictures to display