


RENAULT Grand Scenic: 1FFW100

Vinnumber:	VF1JZ14P649136731	Versionname:	GRAND SCENIC Bose Ed.7pl.110PK
First Registrationdate:	18/06/2013	Fiscalpower:	
Expertise Mileage:	129034	Power Kw:	81
Bodytype:		Body color	Black
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Maintenance	OK	Parking lot	4223
Battery functioning	Yes		
Number of doors	5		
Number of seats	7		
Number head rests	7		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		

Options

Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	SD	Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	Tow bar fixed
Cruise Control			
Steering wheel multifunctional			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining semi-leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/55/17/95 V LightMetal			
Summer tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Continental: 0 mm	Re.R.	Continental: 6 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	527,80
-------------------	---------------

Door F L, Bump(s), PDR - Knock out without painting	63,00
---	--------------



Roof, Scratch(es), Acceptable	0,00
-------------------------------	-------------

No pictures to display

Door R L, Bump(s), Acceptable	0,00
-------------------------------	-------------

No pictures to display

Door F R, Bump(s), PDR - Knock out without painting	63,00
---	--------------



Bumper R, Bump(s) and scratch(es), LI - Repair and paint (complete)

211,80



Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete)

95,00



Alloy rim F L polished, Scratch(es), LI - Repair and paint (complete)

95,00



Roof pillar R, Bump(s), Acceptable

0,00

No pictures to display