

SKODA Octavia: 1HCY181			
Vinnumber:	TMBJF7NE4F0022950	Versionname:	OCTAVIA COMBI Ambition
First Registrationdate:	20/06/2014	Fiscalpower:	90PK
Expertise Mileage:	189483	Power Kw:	66
Bodytype:		Body color	Brown
Gearbox:	MAN 5 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Steel
Fueltype:	Diesel	Oil level	OK
Maintenance	OK	Parking lot	4525
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Steel		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options	
Radio CD	Central consol F
GPS storage	Luggage cover
GPS storage	SD Rear parking sensors
Windows electric F	
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Autom climate control

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
	205/55/16/91 V Steel			
Summer tyres:	Fr.L.	Michelin: 3,5 mm	Fr.R.	Michelin: 3,5 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment			
Repair kit	Yes	Compressor	Yes

Total cost ex VAT	883,23
-------------------	---------------


Rear window, Scratch(es), Acceptable	0,00
--------------------------------------	-------------

No pictures to display

Front bumper, Bump(s) and scratch(es), LI - Repair and paint (complete)	211,80
---	---------------



Door R L, Bump(s), PDR - Knock out without painting	63,00
---	--------------




Door F R, Scratch(es), LI - Repair and paint (complete)

318,35



Bonnet, Chemical polution, LI - Repair and paint (complete)

290,08



Wing F R, Scratch(es), Acceptable

0,00

No pictures to display