



VOLKSWAGEN Passat: 1FE0824

Vinnnumber:	WVWZZZ3CZEE001352	Versionname:	PASSAT VAR Comfortline
First Registrationdate:	7/06/2013	Fiscalpower:	136PK
Expertise Mileage:	100112	Power Kw:	100
Bodytype:		Body color:	Brown
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	2613
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD		Sun Roof electric
GPS storage		Panoramic roof
GPS storage	HD	Central consol F
Windows electric F		Luggage cover
Windows electric R		Front parking sensors
Cruise Control		Rear parking sensors
Steering wheel multifunctional		
Seats F heated		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining leather	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	215/55/16/97 W LightMetal			
Summer tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 6,5 mm	Re.R.	Michelin: 6,5 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	616,60
Front bumper, Strained , I - Repair	0,00



Door R L, Scratch(es), Acceptable	0,00
-----------------------------------	-------------

No pictures to display

Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80
---	---------------



Bumper corner R R, Strained , I - Repair 0,00



Tailgate, Scratch(es), Acceptable 0,00

No pictures to display

Rearlight R , Damaged, E - Replace 114,00



Door F R, Bump(s), PDR - Knock out without painting 111,00



Bonnet, Bump(s), PDR - Knock out without painting 154,80



Ceiling, Dirty, Cleaning 25,00



Rearview mirror housing L, Scratch(es), Acceptable 0,00

No pictures to display

Wing R L, Scratch(es), Acceptable

0,00

No pictures to display