



**VOLVO V60: 1NJJ432**

Vinnumber:	<b>YV1FW74C1G1306663</b>	Versionname:	<b>2.0 D2 VOLVO OCEAN RACE</b>
First Registrationdate:	<b>3/03/2016</b>	Fiscalpower:	
Expertise Mileage:	<b>139807</b>	Power Kw:	<b>88</b>
Bodytype:		Body color	<b>Black</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level	<b>OK</b>
Maintenance	<b>OK</b>	Parking lot	<b>4609</b>
Battery functioning	<b>Yes</b>		
Number of doors	<b>5</b>		
Number of seats	<b>5</b>		
Number head rests	<b>5</b>		
Rims summer	<b>Aluminium</b>		
Category	<b>Passenger Car</b>		
Oil level	<b>OK</b>		
Registration Certificate Car (BE)	<b>Yes</b>		

**Options**

Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	<b>HD</b>	Rear parking sensors	
Windows electric F			
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining leather</b>		
Type of climate control	<b>Autom climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>235/40/18/92 H LightMetal</b>			
Summer tyres:	Fr.L.	<b>Other: 3 mm</b>	Fr.R.	<b>Other: 3 mm</b>
	Re.L.	<b>Other: 3 mm</b>	Re.R.	<b>Other: 3 mm</b>

**Assistance equipment**

Emergency spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
-----------------------	------------	------	------------

Total cost ex VAT	<b>380,00</b>
-------------------	---------------

Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete)	<b>95,00</b>
---	--------------



Alloy rim R L polished, Scratch(es), LI - Repair and paint (complete)	<b>95,00</b>
---	--------------



Alloy rim F L polished, Scratch(es), LI - Repair and paint (complete)	95,00
---	-------



Bumper R, Scratch(es), Acceptable	0,00
-----------------------------------	------

*No pictures to display*

Alloy rim R R polished, Scratch(es), LI - Repair and paint (complete)	95,00
---	-------

