



VOLKSWAGEN Golf: 1FRR631			
Vinnumber:	WVWZZZAUZEP520870	Versionname:	GOLF VAR Trendline 105PK
First Registrationdate:	3/10/2013	Fiscalpower:	
Expertise Mileage:	167250	Power Kw:	77
Bodytype:	Break	Body color:	Brown
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	4706
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		

Options			
Radio CD		Central consol F	
GPS storage	SD	Luggage cover	
GPS storage		Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		
Adaptive cruise control			

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear					
	195/65/15/91 H Steel				
Summer tyres:	Fr.L.	Michelin: 3 mm	Fr.R.	Michelin: 3 mm	
	Re.L.	Michelin: 3 mm	Re.R.	Michelin: 3 mm	

Assistance equipment			
Spare wheel	Yes	Jack	Yes
Total cost ex VAT			226,80
Wheel cover F R, Scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Door F L, Bump(s) and scratch(es), Acceptable			0,00



Maintenance book, Missing, E - Replace			0,00
--	--	--	-------------



Door R R, Bump(s), Acceptable	0,00
-------------------------------	------

No pictures to display

Foglight L, Stone chip(s), Acceptable	0,00
---------------------------------------	------

No pictures to display

Seat cover R R, Stain, Cleaning	15,00
---------------------------------	-------



Bonnet, Stone chip(s), Acceptable	0,00
-----------------------------------	------

No pictures to display

Bumper R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Rear window, Scratch(es), Acceptable	0,00
--------------------------------------	------

No pictures to display

Wheel cover R L, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Wing F R, Bump(s) and scratch(es), Acceptable	0,00
---	------

No pictures to display

Front bumper, Scratch(es), LI - Repair and paint (complete)	211,80
---	--------



Wing R L, Bump(s), Acceptable	0,00
-------------------------------	------

No pictures to display