



VOLVO V40: 1GFU878

Vinnumber:	YV1MV8461E2133135	Versionname:	V40 D2 Base 115PK
First Registrationdate:	28/01/2014	Fiscalpower:	
Expertise Mileage:	151706	Power Kw:	84
Bodytype:	Break	Body color:	Blue
Gearbox:	MAN 6 VIT	Paint type:	Opaque
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	NOT OK	Parking lot:	4324
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F
GPS storage		Luggage cover
GPS storage	HD	Rear parking sensors
Windows electric F		
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining leather and alcantara	
Type of climate control	Autom climate control	
Sport seats		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	NOT OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/50/17/93 H LightMetal			
Winter tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Uniroyal: 6 mm	Re.R.	Uniroyal: 6 mm

Assistance equipment

Repair kit	No	Compressor	Yes
------------	-----------	------------	------------


Total cost ex VAT	929,00
-------------------	--------

Door panel R L, Tear, E - Replace	114,00
-----------------------------------	--------





Wing R R, Chemical polution, LI - Repair and paint (complete) 308,20



Tyre repair kit, Incomplete, Acceptable 0,00

No pictures to display

Boot cover, Damaged, E - Replace 50,00



Interior, Dirty, Acceptable 0,00

No pictures to display

Alloy rim R L polished, Scratch(es), Acceptable 0,00

No pictures to display

Maintenance, Maintenance, Execute 0,00

No pictures to display

Alloy rim F L polished, Scratch(es), LI - Repair and paint (complete) 95,00



Bumper R, Scratch(es), Acceptable 0,00

No pictures to display

Front bumper, Scratch(es), LI - Repair and paint (complete) 211,80



Backrest cover F L, Scratch(es), Acceptable 0,00



Ignition key, Missing, E - Replace 150,00

