



**VOLKSWAGEN Transporter: 1JEY648**

Vinnnumber:	<b>WV1ZZZ7HZFX005564</b>	Versionname:	<b>TRANSP.800 B/F SWB</b>
First Registrationdate:	<b>28/11/2014</b>	Fiscalpower:	<b>102PK</b>
Expertise Mileage:	<b>197219</b>	Power Kw:	<b>75</b>
Bodytype:	<b>Transporter</b>	Body color:	<b>White</b>
Gearbox:	<b>MAN 5 VIT</b>	Paint type:	<b>Opaque</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>3511</b>
Number of doors:	<b>4</b>		
Number of seats:	<b>3</b>		
Number head rests:	<b>3</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Light Commercial Vehicle</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD	
Radio multimedia	
Type of headlighting:	<b>Headlighting Halogen</b>
Type of Lining:	<b>Lining fabrics</b>
Type of climate control:	<b>Manual climate control</b>

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>215/65/16/107 R Steel</b>			
Summer tyres:	Fr.L.	<b>Continental: 5 mm</b>	Fr.R.	<b>Continental: 5 mm</b>
	Re.L.	<b>Continental: 5 mm</b>	Re.R.	<b>Continental: 5 mm</b>

**Assistance equipment**

Spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
-------------	------------	------	------------

<b>Total cost ex VAT</b>	<b>374,40</b>
--------------------------	---------------

<b>Wheel cover R L, Missing, E - Replace</b>	<b>22,50</b>
--	--------------



<b>Bumper R, Damaged, E - Replace</b>	<b>329,40</b>
---------------------------------------	---------------



<b>Bonnet, Scratch(es), Acceptable</b>	<b>0,00</b>
--	-------------

*No pictures to display*

<b>Bodywork, Not original part, Acceptable</b>	<b>0,00</b>
--	-------------

*No pictures to display*

<b>Door F L, Scratch(es), Acceptable</b>	<b>0,00</b>
--	-------------

Door F, Scratches, Acceptable 0,00

No pictures to display

Wheel cover F R, Missing, E - Replace 22,50

