



## VOLKSWAGEN Sharan: 1GWA272

Vinnnumber:	<b>WVWZZZ7NZEV035354</b>	Versionname:	<b>SHARAN Comfortline BMT</b>
First Registrationdate:	<b>15/05/2014</b>	Fiscalpower:	<b>DSG 136PK Aut.</b>
Expertise Mileage:	<b>106228</b>	Power Kw:	<b>100</b>
Bodytype:		Body color:	<b>Dark Blue</b>
Gearbox:	<b>Automatic</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>NOT OK</b>	Parking lot:	<b>4222</b>
Maintenance:	<b>UITVOEREN</b>		
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

## Options

Radio CD		Sun Roof electric
GPS storage	<b>HD</b>	Panoramic roof
GPS storage		Central consol F
Windows electric F		Luggage cover
Windows electric R		Front parking sensors
Cruise Control		Rear parking sensors
Steering wheel multifunctional		
Seats F heated		
Radio multimedia		
Type of headlighting	<b>Headlighting Xenon</b>	
Type of GPS	<b>GPS big screen color</b>	
Type of Lining	<b>Lining leather</b>	
Type of climate control	<b>Autom climate control</b>	

## Limited Technical Inspection

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

## Degree of wear

	<b>225/50/17/98 H LightMetal</b>			
Winter tyres:	Fr.L.	<b>Michelin: 5 mm</b>	Fr.R.	<b>Michelin: 5 mm</b>
	Re.L.	<b>Michelin: 7 mm</b>	Re.R.	<b>Michelin: 7 mm</b>

## Assistance equipment

Total cost ex VAT	1049,80
Sunroof cover, Damaged, E - Replace	195,00



Alloy rim R L polished, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Alloy rim R R polished, Scratch(es), LI - Repair and paint (complete)	95,00



Door R R, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim F L polished, Scratch(es), LI - Repair and paint (complete) 95,00



Tailgate, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete) 95,00



Tyre repair kit, Missing, E - Replace 252,64

No pictures to display

Wing R R, Bump(s), PDR - Knock out without painting 63,00



Bumper R, Scratch(es), LI - Repair and paint (complete) 254,16



Maintenance, Maintenance, Execute 0,00

