



VOLVO XC60: 1AIG649			
Vinnnumber:	YV1DZ5251B2187249	Versionname:	XC60 DRIVE Kinetic 163PK
First Registrationdate:	17/01/2011	Fiscalpower:	
Expertise Mileage:	185042	Power Kw:	120
Bodytype:	SUV	Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3423
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options			
Radio CD		Seats electric F L	
Windows electric F		Sun Roof electric	
Windows electric R		Panoramic roof	
Cruise Control		Central consol F	
Steering wheel multifunctional		Luggage cover	
Radio multimedia		Rear parking sensors	
Type of headlighting	Headlighting Halogen	Type of Tow bar	Tow bar fixed
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
	235/60/18/107 V LightMetal			
Summer tyres:	Fr.L.	Continental: 4 mm	Fr.R.	Continental: 4 mm
	Re.L.	Continental: 5 mm	Re.R.	Continental: 5 mm

Assistance equipment	
Emergency spare wheel	Yes Jack Yes
Total cost ex VAT	2359,55
Alloy rim F L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Wing R R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Wing R L, Scratch(es), LI - Repair and paint (complete)	369,84

Front bumper, Scratch(es), LI - Repair and paint (complete)	254,16



Wing F L, Scratch(es), LI - Repair and paint (complete) 264,21



Bonnet, Scratch(es), LI - Repair and paint (complete) 348,09



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Wing F R, Bump(s) and scratch(es), LI - Repair and paint (complete) 264,21



Windscreen, Repaired, Acceptable 0,00

No pictures to display



Door R R, Bump(s) and scratch(es), LI - Repair and paint (complete) 382,02



Door R L, Scratch(es), LI - Repair and paint (complete) 382,02



