



VOLKSWAGEN Passat: 1FV0987

| | | | |
|------------------------------------|--------------------------|--------------|--------------------------------|
| Vinnnumber: | WVWZZZ3CZEE058672 | Versionname: | PASSAT VAR Trendline BM |
| First Registrationdate: | 8/11/2013 | Fiscalpower: | 105PK |
| Expertise Mileage: | 152300 | Power Kw: | 77 |
| Bodytype: | Break | Body color: | Grey |
| Gearbox: | MAN 6 VIT | Paint type: | Metalic |
| Transmission: | Front | Rims summer: | Steel |
| Fueltype: | Diesel | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | 4701 |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Steel | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

Options

| | | |
|--------------------------------|------------------------------|-----------------------|
| Radio CD | | Central consol F |
| GPS storage | HD | Luggage cover |
| GPS storage | | Front parking sensors |
| Windows electric F | | Rear parking sensors |
| Windows electric R | | |
| Cruise Control | | |
| Steering wheel multifunctional | | |
| Type of headlighting | Headlighting Halogen | |
| Type of GPS | GPS big screen color | |
| Type of Lining | Lining fabrics | |
| Type of climate control | Autom climate control | |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| 205/55/16/91 H Steel | | | | |
|----------------------|-------|----------------|-------|----------------|
| Summer tyres: | Fr.L. | Michelin: 5 mm | Fr.R. | Michelin: 5 mm |
| | Re.L. | Michelin: 6 mm | Re.R. | Michelin: 6 mm |

Assistance equipment

| | | | |
|---|------------|------------|------------|
| Repair kit | Yes | Compressor | Yes |
| Total cost ex VAT | | | 305,90 |
| Wing R R, Bump(s) and scratch(es), Acceptable | | | 0,00 |
| <i>No pictures to display</i> | | | |
| Roof, Scratch(es), Acceptable | | | 0,00 |
| <i>No pictures to display</i> | | | |
| Internal Boot Lining R, Scratch(es), Acceptable | | | 0,00 |
| <i>No pictures to display</i> | | | |
| Wheel cover F L, Scratch(es), Acceptable | | | 0,00 |
| <i>No pictures to display</i> | | | |
| Bumper R, Scratch(es), Acceptable | | | 0,00 |
| <i>No pictures to display</i> | | | |
| Rear bulkhead lining, Scratch(es), Acceptable | | | 0,00 |
| <i>No pictures to display</i> | | | |
| Trunk lid covering R, Scratch(es), E - Replace | | | 155,90 |



| | |
|--|--------|
| Wheel cover F R, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Windscreen, Repaired, Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Door F R, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Bonnet, Bump(s), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Wing F L, Stone chip(s), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Wheel cover R L, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Ignition key, Missing, E - Replace | 150,00 |



| | |
|----------------------------------|------|
| Door panel F L, Worn, Acceptable | 0,00 |
|----------------------------------|------|



| | |
|--|------|
| Tailgate, Bump(s), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Wing F R, Stone chip(s), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Wheel cover R R, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |