



## VOLKSWAGEN Passat: 1HDA999

|                                    |                          |              |                               |
|------------------------------------|--------------------------|--------------|-------------------------------|
| Vinnumber:                         | <b>WVWZZZ3CZFE000471</b> | Versionname: | <b>PASSAT VAR Comfortline</b> |
| First Registrationdate:            | <b>23/06/2014</b>        | Fiscalpower: | <b>136PK</b>                  |
| Expertise Mileage:                 | <b>101277</b>            | Power Kw:    | <b>100</b>                    |
| Bodytype:                          |                          | Body color:  | <b>Gold</b>                   |
| Gearbox:                           | <b>MAN 6 VIT</b>         | Paint type:  | <b>Metalic</b>                |
| Transmission:                      | <b>Front</b>             | Rims summer: | <b>Aluminium</b>              |
| Fueltype:                          | <b>Diesel</b>            | Oil level:   | <b>OK</b>                     |
| Maintenance:                       | <b>OK</b>                | Parking lot: | <b>4104</b>                   |
| Battery functioning:               | <b>Yes</b>               |              |                               |
| Number of doors:                   | <b>5</b>                 |              |                               |
| Number of seats:                   | <b>5</b>                 |              |                               |
| Number head rests:                 | <b>5</b>                 |              |                               |
| Rims summer:                       | <b>Aluminium</b>         |              |                               |
| Category:                          | <b>Passenger Car</b>     |              |                               |
| Oil level:                         | <b>OK</b>                |              |                               |
| Registration Certificate Car (BE): | <b>Yes</b>               |              |                               |

## Options

|                         |                              |                       |                      |
|-------------------------|------------------------------|-----------------------|----------------------|
| Radio CD                |                              | Central consol F      |                      |
| GPS storage             | <b>HD</b>                    | Luggage cover         |                      |
| GPS storage             |                              | Front parking sensors |                      |
| Windows electric F      |                              | Rear parking sensors  |                      |
| Windows electric R      |                              | Type of Tow bar       | <b>Tow bar fixed</b> |
| Cruise Control          |                              |                       |                      |
| Type of headlighting    | <b>Headlighting Halogen</b>  |                       |                      |
| Type of GPS             | <b>GPS big screen color</b>  |                       |                      |
| Type of Lining          | <b>Lining fabrics</b>        |                       |                      |
| Type of climate control | <b>Autom climate control</b> |                       |                      |

## Limited Technical Inspection

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                     |           | Lighting            | <b>OK</b>  |
|                     |           | Wiperblades         | <b>OK</b>  |

## Degree of wear

|               |                                  |                       |       |                       |
|---------------|----------------------------------|-----------------------|-------|-----------------------|
|               | <b>215/55/16/97 V LightMetal</b> |                       |       |                       |
| Summer tyres: | Fr.L.                            | <b>Semperit: 5 mm</b> | Fr.R. | <b>Semperit: 5 mm</b> |
|               | Re.L.                            | <b>Semperit: 8 mm</b> | Re.R. | <b>Semperit: 8 mm</b> |

## Assistance equipment

|            |            |            |            |
|------------|------------|------------|------------|
| Repair kit | <b>Yes</b> | Compressor | <b>Yes</b> |
|------------|------------|------------|------------|

|                   |        |
|-------------------|--------|
| Total cost ex VAT | 997,40 |
|-------------------|--------|

|                                   |      |
|-----------------------------------|------|
| Door F L, Scratch(es), Acceptable | 0,00 |
|-----------------------------------|------|

No pictures to display

|                                     |       |
|-------------------------------------|-------|
| Bumper grille, Damaged, E - Replace | 32,40 |
|-------------------------------------|-------|



|   |        |
|---|--------|
| Front bumper, Scratch(es), LI - Repair and paint (complete) | 211,80 |
|---|--------|



Bumper R, Scratch(es), Acceptable 0,00

No pictures to display

Rear window, Scratch(es), E - Replace 370,00



Wing R R, Bump(s) and scratch(es), LI - Repair and paint (complete) 308,20



Door R L, Bump(s), PDR - Knock out without painting 75,00

