



VOLKSWAGEN Sharan: 1GNT757			
Vinnnumber:	WVWZZZ7NZEVO29396	Versionname:	SHARAN Comfortline BMT
First Registrationdate:	20/03/2014	Fiscalpower:	115PK
Expertise Mileage:	180299	Power Kw:	85
Bodytype:		Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3731
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options			
Radio CD		Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Type of Tow bar	Tow bar fixed
Seats F heated			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear			
Summer tyres:	215/60/16/95 H LightMetal		
	Fr.L.	Fr.R.	
	Continental: 4 mm	Continental: 4 mm	
	Re.L.	Re.R.	
	Michelin: 5 mm	Michelin: 5 mm	

Assistance equipment	
Total cost ex VAT	1569,48
Wing R L, Scratch(es), LI - Repair and paint (complete)	369,84



Sill outer R, Scratch(es), LI - Repair and paint (complete)	372,60
---	--------



Bumper corner R L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Door F R, Bump(s), PDR - Knock out without painting	63,00



Bonnet, Stone chip(s), Acceptable	0,00
<i>No pictures to display</i>	
Door R R, Scratch(es), LI - Repair and paint (complete)	382,02



Tailgate, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Door R L, Scratch(es), LI - Repair and paint (complete)	382,02

