



AUDI A6 AVANT: 1FCL570

Vinnumber:	WAUZZZ4G2DN138198	Versionname:	TDI
First Registrationdate:	24/05/2013	Fiscalpower:	
Expertise Mileage:	98330	Power Kw:	100
Bodytype:		Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	IN 26600 KM	Parking lot:	3303
Maintenance:	OK		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD		Seats electric F L
GPS storage	SD	Central consol F
GPS storage		Luggage cover
Windows electric F		Front parking sensors
Windows electric R		Rear parking sensors
Cruise Control		
Steering wheel multifunctional		
Seats F heated		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining leather	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/55/17/97 Y LightMetal			
Summer tyres:	Fr.L.	Bridgestone: 4 mm	Fr.R.	Bridgestone: 4 mm
	Re.L.	Bridgestone: 7 mm	Re.R.	Bridgestone: 7 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	1975,30
-------------------	----------------

Wing R R, Scratch(es), It - Spot repair	115,56
---	---------------



Alloy rim F L, Scratch(es), LI - Repair and paint (complete)	95,00
--	--------------



Bumper R, Bump(s) and scratch(es), LI - Repair and paint (complete) 302,16



Front bumper, Scratch(es), LI - Repair and paint (complete) 254,16



Alloy rim R L, Scratch(es), LI - Repair and paint (complete) 95,00



Door F R, Bump(s), LI - Repair and paint (complete) 430,02



Rearview mirror housing R, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Door R R, Bump(s) and scratch(es), LI - Repair and paint (complete) 478,02





Alloy rim R R, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Outer door handle R R, Scratch(es), 67 - Polish	55,19
---	-------



Outer door handle F R, Scratch(es), 67 - Polish	55,19
---	-------

