



AUDI A5: 1FCO211			
Vinnnumber:	<b>WAUZZZ8T1DA072483</b>	Versionname:	<b>A5 SB Quattro DPF 245PK</b>
First Registrationdate:	<b>24/05/2013</b>	Fiscalpower:	
Expertise Mileage:	<b>88294</b>	Power Kw:	<b>180</b>
Bodytype:	<b>Hatchback</b>	Body color:	<b>Dark Grey</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>4 Weel</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>3604</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		

Options	
Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Front parking sensors
Cruise Control	Rear parking sensors
Steering wheel multifunctional	
Seats F heated	
Radio multimedia	
Type of headlighting	<b>Headlighting Xenon</b>
Type of GPS	<b>GPS big screen color</b>
Type of Lining	<b>Lining leather</b>
Type of climate control	<b>Autom climate control</b>
Sport seats	

Limited Technical Inspection			
Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

Degree of wear				
Summer tyres:	<b>255/35/19/96 Y LightMetal</b>			
	Fr.L.	<b>Pirelli: 5 mm</b>	Fr.R.	<b>Pirelli: 5 mm</b>
	Re.L.	<b>Pirelli: 5 mm</b>	Re.R.	<b>Pirelli: 5 mm</b>

Assistance equipment			
Emergency spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
Total cost ex VAT			<b>190,00</b>
Front bumper, Scratch(es), Acceptable			<b>0,00</b>
<i>No pictures to display</i>			
Alloy rim R L, Scratch(es), LI - Repair and paint (complete)			<b>95,00</b>



Bonnet, Bump(s), Acceptable			<b>0,00</b>
<i>No pictures to display</i>			
Alloy rim F R, Scratch(es), LI - Repair and paint (complete)			<b>95,00</b>



Alloy rim R R, Scratch(es), Acceptable

0,00

*No pictures to display*