



**AUDI A4: 1GSD271**

|                                    |                          |              |                                    |
|------------------------------------|--------------------------|--------------|------------------------------------|
| Vinnnumber:                        | <b>WAUZZZ8KXEA136433</b> | Versionname: | <b>A4 AVANT Multitr.150PK Aut.</b> |
| First Registrationdate:            | <b>14/04/2014</b>        | Fiscalpower: |                                    |
| Expertise Mileage:                 | <b>137506</b>            | Power Kw:    | <b>110</b>                         |
| Bodytype:                          | <b>Break</b>             | Body color:  | <b>Grey</b>                        |
| Gearbox:                           | <b>MAN 6 VIT</b>         | Paint type:  | <b>Metalic</b>                     |
| Transmission:                      |                          | Rims summer: | <b>Aluminium</b>                   |
| Fueltype:                          | <b>Diesel</b>            | Oil level:   | <b>OK</b>                          |
| Battery functioning:               | <b>Yes</b>               | Parking lot: | <b>4527</b>                        |
| Number of doors:                   | <b>5</b>                 |              |                                    |
| Number of seats:                   | <b>5</b>                 |              |                                    |
| Number head rests:                 | <b>5</b>                 |              |                                    |
| Rims summer:                       | <b>Aluminium</b>         |              |                                    |
| Category:                          | <b>Passenger Car</b>     |              |                                    |
| Oil level:                         | <b>OK</b>                |              |                                    |
| Registration Certificate Car (BE): | <b>Yes</b>               |              |                                    |

**Options**

|                                |                                     |                          |
|--------------------------------|-------------------------------------|--------------------------|
| Radio CD                       | Central consol F                    |                          |
| Windows electric F             | Luggage cover                       |                          |
| Windows electric R             | Rear parking sensors                |                          |
| Cruise Control                 | Type of Tow bar                     | <b>Tow bar removable</b> |
| Steering wheel multifunctional |                                     |                          |
| Seats F heated                 |                                     |                          |
| Radio multimedia               |                                     |                          |
| Type of headlighting           | <b>Headlighting Xenon</b>           |                          |
| Type of GPS                    | <b>GPS big screen color</b>         |                          |
| Type of Lining                 | <b>Lining leather and alcantara</b> |                          |
| Type of climate control        | <b>Autom climate control</b>        |                          |
| Sport seats                    |                                     |                          |

**Limited Technical Inspection**

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                     |           | Lighting            | <b>OK</b>  |
|                     |           | Wiperblades         | <b>OK</b>  |

**Degree of wear**

|               |                                  |                          |       |                          |
|---------------|----------------------------------|--------------------------|-------|--------------------------|
|               | <b>225/55/16/95 W LightMetal</b> |                          |       |                          |
| Summer tyres: | Fr.L.                            | <b>Bridgestone: 5 mm</b> | Fr.R. | <b>Bridgestone: 5 mm</b> |
|               | Re.L.                            | <b>Continental: 6 mm</b> | Re.R. | <b>Continental: 6 mm</b> |

**Assistance equipment**

|                       |            |
|-----------------------|------------|
| Emergency spare wheel | <b>Yes</b> |
|-----------------------|------------|

|   |        |
|---|--------|
| Total cost ex VAT                                       | 838,35 |
| Door F R, Scratch(es), LI - Repair and paint (complete) | 318,35 |



|                                   |      |
|-----------------------------------|------|
| Bonnet, Stone chip(s), Acceptable | 0,00 |
|-----------------------------------|------|

No pictures to display

|   |        |
|---|--------|
| Wing R L, Scratch(es), LI - Repair and paint (complete) | 308,20 |
|---|--------|



|   |        |
|---|--------|
| Bumper R, Scratch(es), LI - Repair and paint (complete) | 211,80 |
|---|--------|

