


**BMW 1: 1GXQ782**

Vinnnumber:	<b>WBA1N31020J711647</b>	Versionname:	<b>1 SPORTSHATCH 116d</b>
First Registrationdate:	<b>28/05/2014</b>	Fiscalpower:	<b>Eff.Dyn.Ed.116PK</b>
Expertise Mileage:	<b>122053</b>	Power Kw:	<b>85</b>
Bodytype:		Body color	<b>Black</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type	<b>Metalic</b>
Transmission:	<b>Back</b>	Rims summer	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level	<b>OK</b>
Maintenance	<b>IN 9000 KM</b>	Parking lot	<b>4206</b>
Maintenance	<b>OK</b>		
Battery functioning	<b>Yes</b>		
Number of doors	<b>3</b>		
Number of seats	<b>5</b>		
Number head rests	<b>5</b>		
Rims summer	<b>Aluminium</b>		
Category	<b>Passenger Car</b>		
Oil level	<b>OK</b>		
Registration Certificate Car (BE)	<b>Yes</b>		

**Options**

Radio CD		Central consol F
GPS storage		Luggage cover
GPS storage	<b>HD</b>	Rear parking sensors
Windows electric F		
Cruise Control		
Steering wheel multifunctional		
Type of headlighting	<b>Headlighting Halogen</b>	
Type of GPS	<b>GPS big screen color</b>	
Type of Lining	<b>Lining leather</b>	
Type of climate control	<b>Manual climate control</b>	

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>205/55/16/91 W LightMetal</b>			
Summer tyres:	Fr.L.	<b>Michelin: 5 mm</b>	Fr.R.	<b>Michelin: 5 mm</b>
	Re.L.	<b>Michelin: 3,5 mm</b>	Re.R.	<b>Michelin: 3,5 mm</b>

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
------------	------------	------------	------------

Total cost ex VAT	<b>268,20</b>
-------------------	---------------

Alloy rim F R, Scratch(es), Acceptable	<b>0,00</b>
--	-------------

*No pictures to display*

Door F L, Bump(s), PDR - Knock out without painting	<b>82,80</b>
---	--------------



Front bumper, Scratch(es), Acceptable	<b>0,00</b>
---------------------------------------	-------------

*No pictures to display*

Door F R, Bump(s), PDR - Knock out without painting	<b>122,40</b>
---	---------------



Wing F R, Bump(s), PDR - Knock out without painting

63,00



Rear window, Scratch(es), Acceptable

0,00

*No pictures to display*