



BMW 3: 1HRS111

Vinnumber:	WBA3K11000F835098	Versionname:	3 TOURING 318d 136PK
First Registrationdate:	16/09/2014	Fiscalpower:	
Expertise Mileage:	163642	Power Kw:	100
Bodytype:		Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	2511
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F
GPS storage		Luggage cover
GPS storage	HD	Front parking sensors
Windows electric F		Rear parking sensors
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Seats F heated		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining leather	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK


Degree of wear

	225/50/17/98 Y LightMetal			
Summer tyres:	Fr.L.	Semperit: 9,9 mm	Fr.R.	Semperit: 9,9 mm
	Re.L.	Semperit: 9,9 mm	Re.R.	Semperit: 9,9 mm

Assistance equipment

Total cost ex VAT	327,36
Bumper F L, Scratch(es), It - Spot repair	115,56



Alloy rim F R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Door R R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80
	
Door F R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Door frame R R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	