


**BMW 3: 1FDU772**

Vinnnumber:	<b>WBA3K11060F824512</b>	Versionname:	<b>3 TOURING 318d 136PK</b>
First Registrationdate:	<b>3/06/2013</b>	Fiscalpower:	
Expertise Mileage:	<b>100031</b>	Power Kw:	<b>100</b>
Bodytype:	<b>Break</b>	Body color:	<b>Grey</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:		Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>1111</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		

**Options**

Radio CD	Sun Roof electric
Windows electric F	Panoramic roof
Windows electric R	Central consol F
Steering wheel multifunctional	Luggage cover
Radio multimedia	
Type of headlighting	<b>Headlighting Halogen</b>
Type of GPS	<b>GPS big screen color</b>
Type of Lining	<b>Lining fabrics</b>
Type of climate control	<b>Autom climate control</b>

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>205/60/16/96 H Steel</b>			
Summer tyres:	Fr.L.	<b>Goodyear: 6 mm</b>	Fr.R.	<b>Goodyear: 6 mm</b>
	Re.L.	<b>Bridgestone: 5 mm</b>	Re.R.	<b>Bridgestone: 5 mm</b>

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
		Jack	<b>Yes</b>

Total cost ex VAT	<b>2273,76</b>
Wheel cover F L, Scratch(es), Acceptable	<b>0,00</b>
<i>No pictures to display</i>	
Wing R R, Scratch(es), LI - Repair and paint (complete)	<b>308,20</b>



Bumper R, Bump(s) and scratch(es), LI - Repair and paint (complete)	<b>211,80</b>
---	---------------



Bonnet, Scratch(es), Acceptable 0,00

No pictures to display

Door F L, Scratch(es), Acceptable 0,00

No pictures to display

Door R L, Scratch(es), LI - Repair and paint (complete) 318,35



Door F R, Bump(s) and scratch(es), LI - Repair and paint (complete) 318,35



Roof, Bump(s) and scratch(es), LI - Repair and paint (complete) 481,50



Rear spoiler, Scratch(es), LI - Repair and paint (complete) 115,56



Wheel cover F R, Scratch(es), Acceptable 0,00

No pictures to display

Wing R L, Bump(s) and scratch(es), LI - Repair and paint (complete) 308,20



Front bumper, Scratch(es), LI - Repair and paint (complete) 211,80



Front bumper, Scratch(es), LI - Repair and paint (complete) 211,80

