



BMW 5: 1HFB600			
Vinnnumber:	WBA5J31000D073832	Versionname:	5 TOURING 520d 163PK
First Registrationdate:	4/07/2014	Fiscalpower:	
Expertise Mileage:	113348	Power Kw:	120
Bodytype:	Break	Body color:	White
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4230
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options			
Radio CD		Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunction		Type of Tow bar	Tow bar fixed
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting LED		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
	225/55/17/97 Y LightMetal			
Summer tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm

Assistance equipment			
Repair kit	Yes	Compressor	Yes
Total cost ex VAT			888,32
Alloy rim F L, Scratch(es), LI - Repair and paint (complete)			95,00



Alloy rim R L, Scratch(es), LI - Repair and paint (complete)			95,00
---	--	--	--------------



Bumper R, Bump(s) and scratch(es), LI - Repair and paint (complete) 254,16



Wing F L, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Front bumper, Bump(s) and scratch(es), LI - Repair and paint (complete) 254,16



Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00

