



CITROEN BERLINGO: 1RVD167

| | | | |
|------------------------------------|--------------------------|--------------|---------------|
| Vinnumber: | VF77BBHY6GJ888820 | Versionname: | |
| First Registrationdate: | 9/03/2017 | Fiscalpower: | |
| Expertise Mileage: | 31361 | Power Kw: | 73 |
| Bodytype: | Transporter | Body color: | White |
| Gearbox: | MAN 5 VIT | Paint type: | Opaque |
| Transmission: | Front | Rims summer: | Steel |
| Fueltype: | Diesel | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | 2124 |
| Number of doors: | 5 | | |
| Number of seats: | 3 | | |
| Number head rests: | 3 | | |
| Rims summer: | Steel | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

Options

| | |
|--------------------------------|-------------------------------|
| Radio CD | |
| Windows electric F | |
| Cruise Control | |
| Steering wheel multifunctional | |
| Radio multimedia | |
| Type of headlighting: | Headlighting Halogen |
| Type of Lining: | Lining fabrics |
| Type of climate control: | Manual climate control |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|---------------|-----------------------------|--------------------|-------|--------------------|
| | 195/65/15/91 T Steel | | | |
| Summer tyres: | Fr.L. | Other: 4 mm | Fr.R. | Other: 4 mm |
| | Re.L. | Other: 5 mm | Re.R. | Other: 5 mm |

Assistance equipment


| | | | |
|-------------|------------|------|------------|
| Spare wheel | Yes | Jack | Yes |
|-------------|------------|------|------------|

| | |
|--------------------------|---------------|
| Total cost ex VAT | 364,20 |
|--------------------------|---------------|

| | |
|------------------------------------------------|---------------|
| Front bumper, Scratch(es), Smart repair | 110,64 |
|------------------------------------------------|---------------|



| | |
|------------------------------------------------------------|--------------|
| Wing R R, Bump(s), PDR - Knock out without painting | 63,00 |
|------------------------------------------------------------|--------------|



Boot carpet, Damaged, E - Replace 75,00



Roof, Bump(s), Acceptable 0,00

No pictures to display

Sidewall RL (LCV), Bump(s), It - Spot repair 115,56

