



**BMW 3: 1GGL555**

Vinnumber:	<b>WBA3K91080F933617</b>	Versionname:	<b>3 TOURING 316d 116PK</b>
First Registrationdate:	<b>3/02/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>169470</b>	Power Kw:	<b>85</b>
Bodytype:	<b>Break</b>	Body color:	<b>Grey</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:		Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>1307</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Rear parking sensors
Cruise Control	
Steering wheel multifunctional	
Seats F heated	
Radio multimedia	
Type of headlighting:	<b>Headlighting Halogen</b>
Type of GPS:	<b>GPS big screen color</b>
Type of Lining:	<b>Lining leather</b>
Type of climate control:	<b>Autom climate control</b>

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

<b>205/60/16/92 V LightMetal</b>			
Summer tyres:	Fr.L. <b>Uniroyal: 5 mm</b>	Fr.R. <b>Uniroyal: 5 mm</b>	
	Re.L. <b>Uniroyal: 6 mm</b>	Re.R. <b>Uniroyal: 6 mm</b>	

**Assistance equipment**


Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
------------	------------	------------	------------

<b>Total cost ex VAT</b>	<b>306,80</b>
--------------------------	---------------

<b>Front bumper, Bump(s) and scratch(es), LI - Repair and paint (complete)</b>	<b>211,80</b>
--	---------------



<b>Door R L, Scratch(es), Acceptable</b>	<b>0,00</b>
--	-------------

<i>No pictures to display</i>		
Alloy rim R R, Scratch(es), LI - Repair and paint (complete)		95,00
		
Bonnet, Stone chip(s), Acceptable		0,00
<i>No pictures to display</i>		
Bumper R, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		