


**BMW 3: 1FH0809**

Vinnumber:	<b>WBA3K91070F930899</b>	Versionname:	<b>3 TOURING 316d 116PK</b>
First Registrationdate:	<b>1/07/2013</b>	Fiscalpower:	
Expertise Mileage:	<b>174552</b>	Power Kw:	<b>85</b>
Bodytype:	<b>Break</b>	Body color:	<b>Light Blue</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:		Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>2404</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		

**Options**

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Rear parking sensors
Cruise Control	
Steering wheel multifunctional	
Type of headlighting	<b>Headlighting Halogen</b>
Type of Lining	<b>Lining fabrics</b>
Type of climate control	<b>Autom climate control</b>

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

205/50/16/92 H Steel				
Summer tyres:	Fr.L.	<b>Bridgestone: 4 mm</b>	Fr.R.	<b>Bridgestone: 4 mm</b>
	Re.L.	<b>Michelin: 2 mm</b>	Re.R.	<b>Michelin: 2 mm</b>

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
------------	------------	------------	------------

 Total cost ex VAT 1369,35

 Wing R L, Bump(s) and scratch(es), LI - Repair and paint (complete) 308,20

 Wheel cover R R, Scratch(es), Acceptable 0,00

No pictures to display

 Rearview mirror housing R, Scratch(es), Acceptable 0,00

No pictures to display

Interior, Dirty, Cleaning 0,00



Roof, Bump(s), PDR - Knock out without painting 63,00



Wheel cover F L, Scratch(es), Acceptable 0,00

No pictures to display

Door panel F L, Damaged, Smart repair 110,64



Bumper R, Bump(s) and scratch(es), LI - Repair and paint (complete) 211,80



Door R L, Scratch(es), LI - Repair and paint (complete) 318,35



Rocker panel inner R L, Scratch(es), LI - Repair and paint (complete) 115,56



Wheel cover F R, Damaged, E - Replace 30,00



Wing R R, Bump(s) and scratch(es), Acceptable 0,00

No pictures to display

Front bumper, Bump(s) and scratch(es), LI - Repair and paint (complete) 211,80

