



**BMW 1 HATCH: 1NDR021**

Vinnumber:	<b>WBA1V91010V493079</b>	Versionname:	<b>1.5 116D</b>
First Registrationdate:	<b>29/01/2016</b>		<b>EFFICIENTDYNAMICS</b>
Expertise Mileage:	<b>50276</b>		<b>EDIT. (85KW)</b>
Bodytype:	<b>Hatchback</b>	Fiscalpower:	
Gearbox:	<b>MAN 6 VIT</b>	Power Kw:	<b>85</b>
Transmission:	<b>Back</b>	Body color	<b>Silver</b>
Fueltype:	<b>Diesel</b>	Paint type	<b>Metalic</b>
Battery functioning	<b>Yes</b>	Rims summer	<b>Aluminium</b>
Number of doors	<b>5</b>	Oil level	<b>OK</b>
Number of seats	<b>5</b>	Parking lot	<b>2714</b>
Number head rests	<b>5</b>		
Rims summer	<b>Aluminium</b>		
Category	<b>Passenger Car</b>		
Oil level	<b>OK</b>		
Registration Certificate Car (BE)	<b>Yes</b>		

**Options**

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Rear parking sensors
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	<b>Headlighting Halogen</b>
Type of Lining	<b>Lining fabrics</b>
Type of climate control	<b>Autom climate control</b>

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>205/55/16/91 V LightMetal</b>			
Summer tyres:	Fr.L.	<b>Michelin: 4 mm</b>	Fr.R.	<b>Michelin: 4 mm</b>
	Re.L.	<b>Michelin: 4 mm</b>	Re.R.	<b>Michelin: 4 mm</b>

**Assistance equipment**

Total cost ex VAT	570,00
Front bumper, Scratch(es), LI - Repair and paint (complete)	211,80



Bumper R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Interior, Dirty, Cleaning	50,00



Wing R R, Scratch(es), LI - Repair and paint (complete)

308,20

