


BMW 518: 1HDU590

Vinnnumber:	WBA5J11000D065718	Versionname:	TOURING 518dA 143PK
First Registrationdate:	26/06/2014	Fiscalpower:	Aut.
Expertise Mileage:	156383	Power Kw:	105
Bodytype:	Break	Body color:	Grey
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OVER 5000 KM	Parking lot:	2702
Maintenance:	OK		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Seats electric F L
GPS storage	HD	Seats electric F R
GPS storage		Central consol F
Windows electric F		Luggage cover
Windows electric R		Front parking sensors
Cruise Control		Rear parking sensors
Steering wheel multifunctional		
Seats F heated		
Radio multimedia		
Type of headlighting	Headlighting Xenon	
Type of GPS	GPS big screen color	
Type of Lining	Lining leather	
Type of climate control	Autom climate control	
Head-up Display		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/55/17/97 Y LightMetal			
Summer tyres:	Fr.L.	Michelin: 6 mm	Fr.R.	Michelin: 6 mm
	Re.L.	Bridgestone: 6 mm	Re.R.	Bridgestone: 6 mm

Assistance equipment

Repair kit	No	Compressor	Yes
------------	-----------	------------	------------

Total cost ex VAT 1022,64

Maintenance, Maintenance, P - Check 0,00

Alloy rim F L, Scratch(es), Acceptable 0,00



Door R L, Bump(s), Acceptable 0,00



Bumper R, Scratch(es), Acceptable 0,00



Tyre repair kit, Missing, E - Replace 252,64



Alloy rim R R, Scratch(es), Acceptable 0,00



Wing R L, Bump(s) and scratch(es), LI - Repair and paint (complete) 465,84



Front bumper, Scratch(es), LI - Repair and paint (complete) 254,16



Windscreen, Scratch(es), E - Replace 0,00



Ceiling, Stain, Cleaning 50,00



Door R R, Scratch(es), Acceptable 0,00

