



MERCEDES B: BWM056

| | | | |
|-------------------------|--------------------------|--------------|------------------|
| Vinnumber: | WDD2452071J013435 | Versionname: | |
| First Registrationdate: | 1/07/2005 | Fiscalpower: | |
| Expertise Mileage: | 140246 | Power Kw: | 80 |
| Bodytype: | | Body color: | Black |
| Gearbox: | MAN 6 VIT | Paint type: | Metalic |
| Transmission: | Front | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Maintenance: | OK | Parking lot: | 2826 |
| Battery functioning: | Yes | | |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |

Options

| | | |
|-------------------------|------------------------------|-----------------------|
| Radio CD | | Central consol F |
| Windows electric F | | Luggage cover |
| Type of headlighting | Headlighting Halogen | Front parking sensors |
| Type of Lining | Lining leather | Rear parking sensors |
| Type of climate control | Autom climate control | |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|---------------|----------------------------------|-------------------------|-------|-------------------------|
| | 205/55/16/91 H LightMetal | | | |
| Winter tyres: | Fr.L. | Michelin: 4 mm | Fr.R. | Michelin: 4 mm |
| | Re.L. | Michelin: 5,5 mm | Re.R. | Michelin: 5,5 mm |

Assistance equipment

| | | | |
|-----------------------|------------|------|------------|
| Emergency spare wheel | Yes | Jack | Yes |
|-----------------------|------------|------|------------|

| | |
|--------------------------|----------------|
| Total cost ex VAT | 1974,12 |
|--------------------------|----------------|

| | |
|---|--------------|
| Alloy rim F R, Scratch(es), LI - Repair and paint (complete) | 95,00 |
|---|--------------|



| | |
|--|---------------|
| Door R L, Scratch(es), LI - Repair and paint (complete) | 308,20 |
|--|---------------|



| | |
|---|---------------|
| Rearview mirror housing R, Scratch(es), LI - Repair and paint (complete) | 115,56 |
|---|---------------|



Door R R, Scratch(es), LI - Repair and paint (complete) 318,35



Door F R, Scratch(es), LI - Repair and paint (complete) 318,35



Wing R R, Scratch(es), Acceptable 0,00

No pictures to display

Wing F L, Scratch(es), LI - Repair and paint (complete) 220,18



Door F L, Scratch(es), Acceptable 0,00

No pictures to display

Mirror side blinker L, Crack, E - Replace 30,00



Mirror side blinker R, Missing, E - Replace 30,00



Door panel F L, Stain, Cleaning 25,00



Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80





Tailgate, Scratch(es), LI - Repair and paint (complete)

301,68

