



**FIAT Freemont: FG5497**

Vinnnumber:	<b>3C4PFACY3ET214916</b>	Versionname:	<b>FREEMONT Lounge 136PK</b>
First Registrationdate:	<b>12/04/2016</b>	Fiscalpower:	
Expertise Mileage:	<b>123456789</b>	Power Kw:	<b>100</b>
Bodytype:		Body color:	<b>White</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Opaque</b>
Transmission:		Rims summer:	<b>Aluminium</b>
Fueltype:		Oil level:	<b>NOT OK</b>
Battery functioning:	<b>No</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>NOT OK</b>		
Registration Certificate Car (BE):	<b>No</b>		

**Options**

Radio CD		Seats electric F L	
Windows electric F		Central consol F	
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of Lining	<b>Lining leather</b>		
Type of climate control	<b>Autom climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>NOT OK</b>	Battery functioning	<b>No</b>
Idle position	<b>NOT OK</b>	Sound engine	<b>NOT OK</b>
Engine startingtime	<b>NOT OK</b>	Transmission	<b>OK</b>
Handbrake	<b>OK</b>	Wiperblades	<b>NOT OK</b>

**Degree of wear**

	<b>225/55/19/99 H LightMetal</b>			
Winter tyres:	Fr.L.	<b>Pirelli: 6 mm</b>	Fr.R.	<b>Pirelli: 6 mm</b>
	Re.L.	<b>Pirelli: 5 mm</b>	Re.R.	<b>Pirelli: 5 mm</b>

**Assistance equipment**

Emergency spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
-----------------------	------------	------	------------

Total cost ex VAT	<b>2261,37</b>
-------------------	----------------

Parking sensor R, Damaged, E - Replace	<b>80,00</b>
--	--------------



Engine protective plate, Hole, E - Replace	<b>25,00</b>
--	--------------



Front bumper, Scratch(es), LI - Repair and paint (complete)	<b>254,16</b>
---	---------------



Wing F L, Rust, LI - Repair and paint (complete) 264,21



Seat cover R R, Deformed, Acceptable 0,00



Rearview mirror L complete, Broken, E - Replace 192,00



Tailgate, Scratch(es), Acceptable 0,00

No pictures to display

Engine, Missing, P - Check 0,00



Foglight L, Damaged, I - Repair 0,00



Rearview mirror housing R, Scratch(es), LI - Repair and paint (complete) 115,56



Cupholder, Damaged, Chemical cleaning 0,00



Roof, Bump(s) and scratch(es), LI - Repair and paint (complete) 769,80



Windscreen, Damaged, E - Replace

560,64

