


MINI Countryman: 1FQD644

Vinnumber:	WMWZD31080WP93036	Versionname:	Cooper D DPF 112PK
First Registrationdate:	20/09/2013	Fiscalpower:	
Expertise Mileage:	172517	Power Kw:	82
Bodytype:		Body color:	Red
Gearbox:	MAN 6 VIT	Paint type:	Opaque
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Luggage cover	
Windows electric F			
Windows electric R			
Type of headlighting	Headlighting Halogen		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	NOT OK	Sound engine	NOT OK
Engine startingtime	NOT OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/60/16/92 H LightMetal			
Winter tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Uniroyal: 8 mm	Re.R.	Uniroyal: 8 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	0,00
Door trim R R, Scratch(es), E - Replace	0,00



Bumper moulding R, Scratch(es), E - Replace	0,00
---	------



Door F L, Bump(s), Acceptable	0,00
-------------------------------	------

No pictures to display

Door R R, Bump(s) and scratch(es), LI - Repair and paint (complete)	0,00
---	------



Engine, Not functioning (well), P - Check 0,00



Wing trim R R, Scratch(es), E - Replace 0,00



Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 0,00

