



BMW X3: 1GUG902

Vinnumber:	WBAWY110300C58522	Versionname:	X3 sDrive18 136PK
First Registrationdate:	2/05/2014	Fiscalpower:	
Expertise Mileage:	147889	Power Kw:	100
Bodytype:		Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	4503
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F
GPS storage	HD	Luggage cover
GPS storage		Front parking sensors
Windows electric F		Rear parking sensors
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining leather	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear


	225/60/17/99 V LightMetal			
Summer tyres:	Fr.L.	Pirelli: 8 mm	Fr.R.	Pirelli: 8 mm
	Re.L.	Pirelli: 8 mm	Re.R.	Pirelli: 8 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT **1617,61**

Door R L, Bump(s) and scratch(es), LI - Repair and paint (complete) **382,02**



Bonnet, Scratch(es), LI - Repair and paint (complete) 348,09



Door frame R L, Scratch(es), Acceptable 0,00

No pictures to display

Seat cover R R, Stain, Cleaning 25,00



Wing R L, Bump(s) and scratch(es), LI - Repair and paint (complete) 369,84



Door panel R L, Damaged, Smart repair 110,64



Alloy rim F R, Scratch(es), Acceptable 0,00

No pictures to display

Door R R, Bump(s) and scratch(es), LI - Repair and paint (complete) 382,02

