


MINI Countryman: 1HFJ587

Vinnumber:	WMWZD31060WS19311	Versionname:	MINI COUNTRYMAN Cooper D DPF 112PK
First Registrationdate:	8/07/2014	Fiscalpower:	
Expertise Mileage:	137529	Power Kw:	82
Bodytype:		Body color	Blue
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	2830
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD		Central consol F
GPS storage	HD	Luggage cover
GPS storage		Rear parking sensors
Windows electric F		
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining leather	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/60/16/92 H LightMetal			
Summer tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	215,39
-------------------	---------------

Rearview mirror housing R, Scratch(es), Acceptable	0,00
--	-------------

No pictures to display

Wing moulding F R, Scratch(es), E - Replace	14,40
---	--------------











Door F R, Bump(s), Acceptable	0,00
-------------------------------	-------------

No pictures to display

Tailgate, Bump(s), Acceptable	0,00
-------------------------------	-------------

No pictures to display

Alloy rim R L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Alloy rim F R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Door F R, Bump(s), PDR - Knock out without painting	82,80
 	
Alloy rim R R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Bonnet, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Bumper R, Scratch(es), 67 - Polish	55,19
  	
  	
Door R R, Bump(s), PDR - Knock out without painting	63,00
