



PEUGEOT 5008: 1BKE781

Vinnnumber:	VF30A9HR8BS029935	Versionname:	5008 Premium FAP BMP 112PK Aut.
First Registrationdate:	20/06/2011	Fiscalpower:	
Expertise Mileage:	161263	Power Kw:	82
Bodytype:		Body color:	Grey
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	2822
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD		Central consol F	
GPS storage	SD	Luggage cover	
GPS storage		Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	Tow bar removable
Cruise Control			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	215/55/16/93 V Steel			
Summer tyres:	Fr.L.	Kleber: 5 mm	Fr.R.	Kleber: 5 mm
	Re.L.	Bridgestone: 4 mm	Re.R.	Bridgestone: 4 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT

	1008,22
--	----------------

Wing R L, Bump(s), PDR - Knock out without painting

	159,00
--	---------------



Bumper R, Scratch(es), LI - Repair and paint (complete)

	211,80
--	---------------





Tailgate, Scratch(es), LI - Repair and paint (complete)

301,68



Maintenance book, Missing, E - Replace

0,00

No pictures to display

Wheel cover R R, Scratch(es), Acceptable

0,00

No pictures to display

Wheel cover F L, Scratch(es), Acceptable

0,00

No pictures to display

Door frame R L, Bump(s) and scratch(es), It - Spot repair

115,56



Aerial, Missing, E - Replace

0,00



Seat cover F L, Worn, Acceptable

0,00



Wing F R, Scratch(es), LI - Repair and paint (complete)

220,18

