


PEUGEOT 3008: KS2910

Vinnnumber:	VF30URHHAES140743	Versionname:	3008 Allure 163PK Aut.
First Registrationdate:	30/06/2014	Fiscalpower:	
Expertise Mileage:	139246	Power Kw:	120
Bodytype:	Hatchback	Body color:	Anthracite
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4118
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Seats electric F L	
Windows electric F		Panoramic roof	
Windows electric R		Central consol F	
Cruise Control		Luggage cover	
Seats F heated		Front parking sensors	
Radio multimedia		Rear parking sensors	
Type of headlighting	Headlighting Xenon		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		
Head-up Display			

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	NOT OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	235/45/18/93 V LightMetal			
Winter tyres:	Fr.L.	Continental: 1 mm	Fr.R.	Continental: 1 mm
	Re.L.	Continental: 4 mm	Re.R.	Continental: 4 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	190,00
Bonnet, Bump(s), Acceptable	0,00
<i>No pictures to display</i>	
Door F R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Alloy rim F L polished, Scratch(es), LI - Repair and paint (complete)	95,00



Bumper R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Alloy rim R R polished, Scratch(es), LI - Repair and paint (complete)	95,00
---	-------

