


RENAULT Espace: 1EYH103

Vinnumber:	VF1JKFJA648654248	Versionname:	Alcantara 149PK
First Registrationdate:	19/04/2013	Fiscalpower:	
Expertise Mileage:	155998	Power Kw:	110
Bodytype:	MPV	Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	3311
Maintenance	GEEN INDICATIE		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	7		
Number head rests:	7		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	No		

Options

Radio CD		Sun Roof electric	
TV/DVD screen R		Panoramic roof	
GPS storage	SD	Central consol F	
GPS storage		Luggage cover	
Windows electric F		Front parking sensors	
Windows electric R		Rear parking sensors	
Cruise Control		Type of Tow bar	Tow bar removable
Steering wheel multifunctional			
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining Alcantara		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/55/17/101 W LightMetal			
Summer tyres:	Fr.L.	Bridgestone: 3 mm	Fr.R.	Bridgestone: 3 mm
	Re.L.	Bridgestone: 5 mm	Re.R.	Bridgestone: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

 Total cost ex VAT 48,00

 Seat cover F L, Worn, P - Check 0,00

 Rearview mirror housing L, Scratch(es), Acceptable 0,00



Alloy rim F R, Scratch(es), Acceptable 0,00



Alloy rim R R, Deformed, Acceptable 0,00



Wing R L, Scratch(es), Acceptable 0,00



Bumper spoiler F, Damaged, E - Replace 48,00



Door F L, Scratch(es), Acceptable 0,00

