



RENAULT Clio: 1GG0025

Vinnnumber:	VF15R040H50242618	Versionname:	CLIO IV BER Expression
First Registrationdate:	3/02/2014	Fiscalpower:	75PK
Expertise Mileage:	66930	Power Kw:	55
Bodytype:	Hatchback	Body color:	Grey
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3222
Number of doors:	5		
Number of seats:	5		
Number head rests:	4		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Windows electric F	Central consol F
Cruise Control	Luggage cover
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting:	Headlighting Halogen
Type of GPS:	GPS big screen color
Type of Lining:	Lining fabrics
Type of climate control:	Manual climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	185/65/15/88 T Steel			
Winter tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 6 mm	Re.R.	Michelin: 6 mm

Assistance equipment


Jack	Yes
------	------------

Total cost ex VAT	2064,74
--------------------------	----------------

Wing R R, Bump(s) and scratch(es), LI - Repair and paint (complete)	246,56
--	---------------



Bonnet, Chemical polution, LI - Repair and paint (complete)	232,06
--	---------------



Wing R L, Bump(s), LI - Repair and paint (complete) 246,56



Wheel cover F R, Damaged, E - Replace 24,00



Ignition key, Missing, E - Replace 150,00

No pictures to display


Wing F R, Scratch(es), LI - Repair and paint (complete) 176,14



Front bumper, Scratch(es), LI - Repair and paint (complete) 169,44



Roof, Chemical polution, LI - Repair and paint (complete) 385,20



Wheel cover F L, Scratch(es), Acceptable 0,00

No pictures to display

Bumper R, Bump(s) and scratch(es), LI - Repair and paint (complete) 169,44





Door R L, Scratch(es), Acceptable 0,00

No pictures to display

Tailgate, Bump(s) and scratch(es), LI - Repair and paint (complete) 241,34



Door F L, Scratch(es), Acceptable 0,00

No pictures to display

Wheel cover R R, Damaged, E - Replace 24,00

