



OPEL Insignia: 1FXC228

Vinnumber:	WOLGT8ES6E1035916	Versionname:	
First Registrationdate:	25/11/2013	Fiscalpower:	
Expertise Mileage:	68212	Power Kw:	103
Bodytype:		Body color:	Brown
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1306
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Windows electric F	Central consol F
Windows electric R	Luggage cover
Cruise Control	Front parking sensors
Steering wheel multifunction	Rear parking sensors
Seats F heated	
Radio multimedia	
Type of headlighting	Headlighting Xenon
Type of Lining	Lining leather
Type of climate control	Autom climate control
Level control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/55/17/97 W LightMetal			
Summer tyres:	Fr.L.	Bridgestone: 4 mm	Fr.R.	Bridgestone: 4 mm
	Re.L.	Bridgestone: 4 mm	Re.R.	Bridgestone: 4 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT 897,68

Bodywork, Damaged, Acceptable 0,00



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00





Windscreen, Repaired, P - Check 0,00



Grill, Broken, E - Replace 105,15



Wing F R, Bad repair, LI - Repair and paint (complete) 220,18



Door R R, Bump(s), PDR - Knock out without painting 63,00



Door F L, Bump(s) and scratch(es), LI - Repair and paint (complete) 414,35

