


PEUGEOT 5008: 1EMN780

Vinnnumber:	VF30A9HD8CS267708	Versionname:	5008 Allure FAP 115PK
First Registrationdate:	23/01/2013	Fiscalpower:	
Expertise Mileage:	153327	Power Kw:	84
Bodytype:	MPV	Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	2118
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD		Panoramic roof
GPS storage	HD	Central consol F
GPS storage		Luggage cover
Windows electric F		Front parking sensors
Windows electric R		Rear parking sensors
Cruise Control		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Type of climate control	Autom climate control	
Head-up Display		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

215/50/17/95 V LightMetal				
Winter tyres:	Fr.L.	Uniroyal: 6 mm	Fr.R.	Uniroyal: 6 mm
	Re.L.	Uniroyal: 8 mm	Re.R.	Uniroyal: 8 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	1591,92
-------------------	----------------

Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80
---	---------------



Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Roof, Bump(s), PDR - Knock out without painting 63,00



Door moulding Lower F R, Scratch(es), Smart repair 110,64



Steering wheel, Worn, P - Check 0,00



Alloy rim R L, Scratch(es), LI - Repair and paint (complete) 95,00



Interior, Dirty, Cleaning 100,00



Door F L, Scratch(es), Acceptable 0,00

Door L, Scratch(es), Acceptable

No pictures to display

Ignition key, Missing, E - Replace 150,00




Front bumper, Scratch(es), LI - Repair and paint (complete) 211,80



Radio, Worn, P - Check 0,00



Tailgate, Bump(s) and scratch(es), LI - Repair and paint (complete) 301,68



Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00



Wing R R, Bump(s), PDR - Knock out without painting 63,00



Wing R L, Scratch(es), Acceptable 0,00

No pictures to display