



PEUGEOT Partner: 1GUH292

Vinnumber:	VF37A9HL0EJ628447	Versionname:	PARTNER B/F L1H1 Conf.120 115PK
First Registrationdate:	2/05/2014	Fiscalpower:	
Expertise Mileage:	186660	Power Kw:	84
Bodytype:	Transporter	Body color:	White
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3105
Number of doors:	5		
Number of seats:	2		
Number head rests:	2		
Rims summer:	Steel		
Category:	Light Commercial Vehicle		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Front parking sensors
Windows electric F		
Cruise Control		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Type of climate control	Manual climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	195/65/15/91 T Steel			
Summer tyres:	Fr.L.	Michelin: 2 mm	Fr.R.	Michelin: 2 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm

Assistance equipment

Spare wheel	Yes
-------------	------------

Total cost ex VAT	1158,67
-------------------	---------

Door R L, Bump(s) and scratch(es), LI - Repair and paint (complete)	238,76
---	--------



Wheel cover R L, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Sill outer L, Bump(s) and scratch(es), LI - Repair and paint (complete)	232,88
---	--------



Wing R L, Scratch(es), LI - Repair and paint (complete) 231,15



Bumper F R, Scratch(es), Acceptable 0,00

No pictures to display

Wheel cover F L, Scratch(es), Acceptable 0,00

No pictures to display

Sill outer R, Bump(s) and scratch(es), LI - Repair and paint (complete) 232,88



Wheel cover F R, Scratch(es), Acceptable 0,00

No pictures to display

Boot carpet, Damaged, E - Replace 123,00



Roof, Bump(s), Acceptable 0,00

No pictures to display

Interior, Dirty, Cleaning 100,00



Wheel cover R R, Scratch(es), Acceptable 0,00

No pictures to display

