



MINI Mini: 1FXB807			
Vinnnumber:	WMWSW11020T771969	Versionname:	MINI One D 90PK DPF
First Registrationdate:	25/11/2013	Fiscalpower:	
Expertise Mileage:	144546	Power Kw:	66
Bodytype:		Body color	Black
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Steel
Fueltype:	Diesel	Oil level	OK
Maintenance	IN 2100 KM		
Maintenance	OK		
Battery functioning	Yes		
Number of doors	3		
Number of seats	4		
Number head rests	4		
Rims summer	Steel		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	No		

Options	
Radio CD	Luggage cover
Windows electric F	
Type of headlighting	Headlighting Halogen
Type of Lining	Lining fabrics
Type of climate control	Manual climate control

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	NOT OK	Sound engine	NOT OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
Summer tyres:	175/65/15/84 H Steel			
	Fr.L.	Continental: 3 mm	Fr.R.	Continental: 3 mm
	Re.L.	Bridgestone: 2,5 mm	Re.R.	Bridgestone: 2,5 mm

Assistance equipment			
Repair kit	Yes	Compressor	Yes
Total cost ex VAT			458,80
Rear window, Scratch(es), E - Replace			370,00



Tailgate, Scratch(es), Acceptable	0,00
No pictures to display	
Door F L, Scratch(es), Acceptable	0,00
No pictures to display	

Wing R L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Wing F L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Steel rim R L, Deformed, E - Replace	88,80
	
Front bumper, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	