



PEUGEOT Partner: 1FPI501

Vinnnumber:	VF37J9HP8DN532660	Versionname:	PARTNER TEPEE 2PLC e-HDi Active BMP 92PK
First Registrationdate:	13/09/2013	Fiscalpower:	
Expertise Mileage:	182192	Power Kw:	68
Bodytype:	Hatchback	Body color:	Black
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3427
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Luggage cover	
Cruise Control		Rear parking sensors	
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/65/15/94 H Steel			
Summer tyres:	Fr.L.	Uniroyal: 2 mm	Fr.R.	Uniroyal: 2 mm
	Re.L.	Uniroyal: 4 mm	Re.R.	Uniroyal: 4 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT	211,80
Front bumper, Scratch(es), LI - Repair and paint (complete)	211,80



Sill outer R, Bump(s) and scratch(es), Le - Replace and paint	0,00
--	-------------



Bumper R, Damaged, Le - Replace and paint	0,00
--	-------------



Wing R L, Scratch(es), Acceptable 0,00

No pictures to display

Sill outer L, Scratch(es), Acceptable 0,00

No pictures to display

Door F L, Bump(s) and scratch(es), Acceptable 0,00

No pictures to display

Tailgate, Bump(s), LI - Repair and paint (complete) 0,00



Door R R, Bump(s), Le - Replace and paint 0,00

