


**PEUGEOT 508: 1FJC022**

Vinnnumber:	<b>VF38ERHR8DL037516</b>	Versionname:	<b>508 SW Active 136PK</b>
First Registrationdate:	<b>12/07/2013</b>	Fiscalpower:	
Expertise Mileage:	<b>171609</b>	Power Kw:	<b>100</b>
Bodytype:		Body color:	<b>Grey</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>OK</b>	Parking lot:	<b>2629</b>
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		

**Options**

Radio CD		Panoramic roof
GPS storage		Central consol F
GPS storage	<b>HD</b>	Luggage cover
Windows electric F		Front parking sensors
Windows electric R		Rear parking sensors
Cruise Control		
Steering wheel multifunctional		
Type of headlighting	<b>Headlighting Halogen</b>	
Type of GPS	<b>GPS big screen color</b>	
Type of Lining	<b>Lining fabrics</b>	
Type of climate control	<b>Autom climate control</b>	

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>215/55/17/92 H LightMetal</b>			
Summer tyres:	Fr.L.	<b>Kleber: 3 mm</b>	Fr.R.	<b>Kleber: 3 mm</b>
	Re.L.	<b>Kleber: 3 mm</b>	Re.R.	<b>Kleber: 3 mm</b>

**Assistance equipment**

Spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
-------------	------------	------	------------

Total cost ex VAT	401,80
-------------------	--------

Door F R, Scratch(es), Acceptable	0,00
-----------------------------------	------

*No pictures to display*

Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete)	95,00
---	-------



Alloy rim R R polished, Scratch(es), LI - Repair and paint (complete)	95,00
---	-------



Wing F L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Bumper R, Bump(s) and scratch(es), LI - Repair and paint (complete)	211,80

