



RENAULT Grand Scenic: 1FFI013

Vinnumber:	VF1JZ14P649069587	Versionname:	GRAND SCENIC Business 7pl.110PK
First Registrationdate:	13/06/2013	Fiscalpower:	
Expertise Mileage:	65050	Power Kw:	81
Bodytype:	MPV	Body color:	Burgundy
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3525
Number of doors:	5		
Number of seats:	7		
Number head rests:	7		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Rear parking sensors
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/60/16/96 H Steel			
Summer tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT	1248,68
-------------------	----------------

Wheel cover F R, Scratch(es), E - Replace	30,00
---	--------------



Door R R, Bump(s), PDR - Knock out without painting	82,80
---	--------------





Front bumper, Scratch(es), Acceptable 0,00

No pictures to display

Roof, Chemical pollution, LI - Repair and paint (complete) 481,50



Wing R L, Bump(s) and scratch(es), LI - Repair and paint (complete) 308,20



Door F L, Bump(s), PDR - Knock out without painting 63,00



Door F R, Bump(s), PDR - Knock out without painting 63,00



Wing F R, Scratch(es), LI - Repair and paint (complete) 220,18

