


**SKODA Octavia: 1GHX539**

Vinnnumber:	<b>TMBAG9NE0E0135267</b>	Versionname:	<b>OCTAVIA BER Elegance</b>
First Registrationdate:	<b>12/02/2014</b>	Fiscalpower:	<b>DSG 105PK Aut.</b>
Expertise Mileage:	<b>131884</b>	Power Kw:	<b>77</b>
Bodytype:	<b>Hatchback</b>	Body color:	<b>Silver</b>
Gearbox:	<b>Automatic</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>4328</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD	Seats electric F L
Windows electric F	Central consol F
Windows electric R	Luggage cover
Cruise Control	Front parking sensors
Steering wheel multifunctional	Rear parking sensors
Seats F heated	
Radio multimedia	
Type of headlighting:	<b>Headlighting Xenon</b>
Type of GPS:	<b>GPS big screen color</b>
Type of Lining:	<b>Lining fabrics</b>
Type of climate control:	<b>Autom climate control</b>

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>225/45/17/91 Y LightMetal</b>			
Summer tyres:	Fr.L.	<b>Kleber: 5 mm</b>	Fr.R.	<b>Kleber: 5 mm</b>
	Re.L.	<b>Kleber: 6 mm</b>	Re.R.	<b>Kleber: 6 mm</b>

**Assistance equipment**

Spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
-------------	------------	------	------------

Total cost ex VAT	422,36
-------------------	--------

Alloy rim R R, Scratch(es), Acceptable	0,00
--	------

*No pictures to display*

Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------





Front bumper, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80
<i>No pictures to display</i>	
Bonnet, Bump(s), Acceptable	0,00
<i>No pictures to display</i>	
Wing F R, Scratch(es), It - Spot repair	115,56

